RH Lester

March 15, 1971

Mr. J. G. McClellan:

Please let me mention again the need for your inspection of the east wall of the High Voltage Laboratory.

Bricks are moving and/or shearing in at least seven areas, in addition to the several-inch movement of the capping stones on top of this wall.

Someone qualified to interpret the significance of this deterioration should, I think, advise us regarding the safety of this wall and the possible need for repairs.

A. Lynn Libby
r